



# HYDROQUIP™

13345 Estelle Street • Corona, CA 92879-1881  
Email: [hq@hydroquip.com](mailto:hq@hydroquip.com) • Internet: <http://www.hydroquip.com/>  
Telephone: 909.273.7575 • Fax: 800.332.7190



The number one cause for repeated tripping of a GFCI breaker on a new install is that the breaker has been incorrectly wired. The illustration below shows a typical installation. Note that the Neutral pigtail is connected at the neutral bus bar and the Neutral wire coming from the spa control system is connected directly to the breaker. Connecting the Neutral wire from the spa control system to the Neutral bus bar will cause the repeated tripping. **WARNING** - The illustration is meant to be used as a guide ONLY. This does not in any way supercede any manufacturers installation instruction.

